


UNDERSTANDING DEVICE LIMITATIONS AND SOLUTIONS

Troubleshooting inappropriate therapy for lead fractures and electromagnetic interference


Key take-away points

- Fractured leads need to be replaced.
- RV lead noise discriminators can prevent inappropriate therapy in lead fractures.
- Patients should not be in close proximity to sources of significant EMI.

Lead fracture



Electromagnetic interference



Notes